



No.	DESCRIPTION	MATERIAL & SPECIFICATION	QTY.	NOTE
44	Screw	ST2.9x14	4	
43	Housing (back)	PP-200K/600S	1	
42	Wire		1	
41	Washer	AMS	1	
40	Screw	ST2.9x30	2	
39	Screw	ST2.9x30	2	
38	Connector	GT2	1	
37	Motor Fastener	POM	1	
36	E-Ring	63Mn	1	
35	Gear Axle Sheath	PBT	1	
34	Motor	HC 6016	1	
33	Motor Axle Sheath	PA66+30%GF	1	
32	Gear	POM	1	
31	Gear Axle	12L14	1	
30	Gear	POM	1	
29	Screw	ST2.9x12	7	
28	Switch Cover Slab	PBT	1	
27	Gear Insert	12L14	1	
26	Spring	65Mn φ0.8	1	
25	Rivet	Cu	2	
24	Switch Board	PA66+30%GF	1	
23	Reed (bottom)	Cu t=0.3	1	
22	Reed (top)	Cu t=0.3	1	
21	Switch		1	
20	Switch Rod	PBT	1	
19	Housing (Front)	PP-200K/600S	1	
18	Driving Wheel	30c13(SIS420)22	1	
17	Housing Insert	12L14	1	
16	Screw	ST2.9x8	1	
15	Blade Rest Link Rod	PA66+30%GF	1	
14	Blade Rest Link Rod Insert	12L14	1	
13	Cover Slab	SPPC	1	
12	Blade	30c13(SIS420)22	1	
11	Leaf Spring	SIS301 T40.6	1	
10	Screw	MAX7	1	
9	Blade Rest	POM	1	
8	Screw	ST2.9x8	8	
7	Screw	M3x8	1	
6	Magnet	Iron Oxides	1	
5	Screw	ST2.2x6	1	
4	Magnet Sheath	PP	1	
3	Press Board	PP	1	
2	Spring	65Mn φ0.3	1	
1	Link Rod	PP	1	